



1949-52 METAL BODY PANELS



1 **1949-52 2-DOOR
ROCKER PANEL**
(DR. SIDE) ORDER #4690L
(PASS. SIDE) ORDER #4690R
\$69 ea.

5 **1949-52 ROCKER EXTENSION**
Fits all models. 11" long.
(DR. SIDE) ORDER #4689L
(PASS. SIDE) ORDER #4689R
\$49 ea.

**1949-52 INNER
ROCKER PANEL
(REPAIR PANEL)**
Repair panel (in correct shape) for
repairing inner rocker panels.
3 ft. long.
Order **\$35**
#4683

2 **1949-52 2-DOOR
ROCKER PANEL WITH
EXTENSION**
(DR. SIDE)
ORDER #4695L
(PASS. SIDE)
ORDER #4695R
\$75 ea.

7 **1949-52 REAR FENDER
REAR SECTION PANEL**
(14" tall, 36" long)
(DR. SIDE) ORDER #4699L
(PASS. SIDE) ORDER #4699R
\$79 ea.

**1949-52 UNDER DECK
LID REPAIR PANEL**
Metal panel to repair the gutter area
where the rear gravel pan attaches to
body of car under the deck lid.
Requires both left and right repair
panels to do entire rear of car.
1949-50
(DR. SIDE) ORDER #4681L
(PASS. SIDE) ORDER #4681R
1951-52
(DR. SIDE) ORDER #4682L
(PASS. SIDE)
ORDER #4682R
\$35 ea.

3 **1949-52 4-DOOR
ROCKER PANEL**
(DR. SIDE) ORDER #4696L
(PASS. SIDE) ORDER #4696R
\$70⁰⁰ ea.

4 **1949-52
4-DOOR ROCKER
PANEL WITH
EXTENSION**
(DR. SIDE)
ORDER #4688L
(PASS. SIDE)
ORDER #4688R
\$125 ea.

8 **1949-50 WHEEL OPENING
REPAIR PANEL**
(DR. SIDE) ORDER #4698L
(PASS. SIDE) ORDER #4698R
**1951-52 WHEEL OPENING
REPAIR PANEL**
(DR. SIDE) ORDER #4684L
(PASS. SIDE) ORDER #4684R
\$35⁰⁰ ea.

Metal panel to repair rusty wheel openings.
This is not one of those "universal" repair
panels. Has correct shape so your 1949-52
fenderskirts fit to a "T".

**1949-52 CHEV SEDAN DELIVERY
LOWER FRONT QUARTER PANEL**
(DR. SIDE) ORDER #4653L
(PASS. SIDE) ORDER #4653R
\$289⁰⁰ pr.

2-piece set
as shown.

1953-54 METAL BODY PANELS




1 1953-54 2-DOOR OUTER ROCKER PANEL WITH EXTENSION

Replace your rusty rocker panels with this fabricated replacement that extends to rear fender flare.

DRIVER SIDE
PASS. SIDE

ORDER #695L
ORDER #695R

\$59⁰⁰ ea.



2 1953-54 2-DOOR REAR QUARTER PANEL FRONT

Replaces metal in front of rear tire under gravel shield.

DRIVER SIDE
ORDER #697L

PASS. SIDE
ORDER #697R

\$35⁰⁰ ea.



1953-54 2-DOOR OUTER ROCKER PANEL

Excellent reproduction rocker panel stamped out just like original. (No extension)

DRIVER SIDE ORDER #690L
PASS. SIDE ORDER #690R

\$125⁰⁰ ea.



1953-54 4-DOOR SEDAN ROCKER PANEL

Fits 4 door Sedans that need rocker panel replacement.

Extends to back edge of rear door.

DRIVER SIDE
PASS. SIDE

ORDER #696L
ORDER #696R

\$59⁰⁰ ea.



1953-54 2-DOOR INNER ROCKER PANEL

Reproductions of metal repair panels do not get any nicer than this. Stamped and cut like originals.

DRIVER SIDE
PASS. SIDE

ORDER #689L
ORDER #689R

\$150⁰⁰ ea.



3 1953-54 WHEEL OPENING REPAIR PANEL

Metal panel to repair rusty wheel openings. This is not one of those "universal" repair panels. It has correct shape so your 1953/54 fendershirts fit to a "T."

DRIVER SIDE
ORDER #698L

PASS. SIDE
ORDER #698R

\$35 ea.



4 1953-54 REAR FENDER REAR SECTION PANEL

Extends around rear to taillight seam.

DRIVER SIDE
PASS. SIDE

ORDER #699L
ORDER #699R

\$70⁰⁰ ea.



5 1953-54 UNDER DECK LID REPAIR PANEL

Metal panel to repair the gutter area where rear gravel pan attaches to body of car, under the deck lid. Requires both left and right repair panels to do entire rear of car.



DRIVER SIDE
ORDER #684L

PASS. SIDE
ORDER #684R

\$24⁰⁰ ea.

1953-54 LOWER FRONT QUARTER PANEL

Extends from door jamb to about half way through wheel well opening and extends about 4" over top of wheel well.

DRIVER SIDE ORDER #682L
PASS. SIDE ORDER #682R

\$209⁰⁰ ea.



1953-54 REAR FENDER REAR SECTION

Fits behind tire.

DRIVER SIDE ORDER #683L
PASS. SIDE ORDER #683R

\$209⁰⁰ ea.

